

## Unit-5

### 1. Introduction to Surface Roughness

Surface roughness is the collection of small irregularities present on a machined surface. These irregularities are produced during manufacturing processes such as turning, milling, grinding, casting, and forging.

#### Importance of Surface Roughness

Affects friction and wear.

Influences fatigue strength.

Determines lubrication effectiveness.

Affects corrosion resistance.

Controls dimensional accuracy and fit between mating parts.

### 2. Surface Texture

Surface texture consists of:

#### 1. Roughness

Small closely spaced irregularities caused by machining.

#### 2. Waviness


Larger irregularities caused by machine vibrations, tool deflection, etc.

#### 3. Flaws

Scratches, cracks, pits, and holes.

#### Surface Texture Diagram

Surface Profile



Roughness

---

## Waviness

### 3. Terminology

#### Actual Surface


The real surface obtained after machining.

#### Nominal Surface

The ideal surface represented in drawings.

#### Datum Line (Mean Line)

Reference line from which roughness measurements are made.



### 4. Surface Roughness Parameters

#### (A) Arithmetic Mean Roughness (Ra)

Most widely used parameter.

Formula:

$$Ra = \frac{|y_1| + |y_2| + |y_3| + \dots + |y_n|}{n}$$

Where:

$y$  = deviation from mean line

$n$  = number of observations

#### Advantages

Easy to calculate.

Internationally accepted.


(B) Root Mean Square Roughness ( $R_q$ )

$$R_q = \sqrt{\frac{y_1^2 + y_2^2 + y_3^2 + \dots + y_n^2}{n}}$$

Provides more weight to larger deviations.

(C) Maximum Peak-to-Valley Height ( $R_t$ )

Difference between highest peak and deepest valley.



$$R_t = \text{Peak} - \text{Valley}$$

## 5. Methods of Surface Roughness Measurement

### 1. Comparison Method

Surface is compared with standard specimens.

#### Procedure

Standard roughness samples are provided.

Workpiece is visually or tactilely compared.

#### Advantages

Simple.


Low cost.

#### Disadvantages

Less accurate.

Depends on operator skill.

### Diagram




## 2. Stylus Method

Most common method.

A diamond stylus moves over the surface and records irregularities.

### Working Principle



### Components

Diamond stylus

Pickup unit

Amplifier

Recorder/display

### Advantages

High accuracy.

Direct reading.


## Disadvantages

Stylus may scratch soft surfaces.

## 6. Taylor Hobson Talysurf Instrument

Most widely used stylus-type instrument.

### Construction



### Working

Stylus traverses over the surface.

Vertical movement is converted into electrical signals.

Signals are amplified.

Roughness profile is displayed.

### Features

Measures Ra, Rq, Rt.

High magnification.

Automatic recording.

### Advantages

Very accurate.

Permanent record available.

---

## 7. Optical Methods

Used where contact measurement is not desirable.

Principle


Light is reflected from the surface and analyzed.

Types

Interference microscope

Optical flat method

Diagram



Advantages


Non-contact method.

Suitable for delicate surfaces.

## 8. Interference Microscope

Uses light interference principle.

Working





### Basic Symbol

/ |  
/ |

### Machining Required

/ |  
/ |  
----- |

### Machining Not Allowed

/ |  
/ |  
----- | O

### Roughness Value Indication

Example:

/ |  
/ |  
1.6

Means:

$R_a = 1.6 \mu\text{m}$   $R_a = 1.6 \mu\text{m}$   $R_a = 1.6 \mu\text{m}$

## 11. Factors Affecting Surface Roughness

### Machine Factors

Vibration

Rigidity

Alignment

Tool Factors

Tool geometry

Tool wear

Tool material

Cutting Conditions

Speed

Feed

Depth of cut

Work Material Factors

Hardness

Ductility

Grain structure

## 12. Applications of Surface Roughness Measurement

Automobile components

Bearings

Gears

Shafts

Aerospace parts

Precision instruments

Medical implants