

## Unit-5

# Surface Roughness Measurement

**1. Surface roughness is the measure of:**

- A) Material hardness
- B) Surface irregularities
- C) Material density
- D) Surface color

**2. Surface roughness is generally produced by:**

- A) Machining processes
- B) Heat treatment only
- C) Welding only
- D) Painting only

**3. The average roughness value is represented by:**

- A) Rc
- B) Rt
- C) Ra
- D) Rp

**4. Which instrument is commonly used to measure surface roughness?**

- A) Vernier Caliper
- B) Micrometer
- C) Surface Roughness Tester (Profilometer)
- D) Height Gauge

**5. Surface roughness is usually expressed in:**

- A) Newton
- B) Micrometers ( $\mu\text{m}$ )
- C) Kilograms
- D) Watts

**6. A smoother surface generally has:**

- A) Higher roughness value
- B) Lower roughness value
- C) Higher hardness
- D) Lower density

**7. Which machining process generally produces the best surface finish?**

- A) Casting
- B) Forging
- C) Grinding
- D) Welding

**8. Surface roughness affects:**

- A) Wear and friction
- B) Appearance only
- C) Weight only
- D) Color only

**9. The stylus method measures roughness by:**

- A) Chemical reaction
- B) Optical reflection
- C) Tracing the surface profile
- D) Heat transfer

**10. Roughness symbols are specified on:**

- A) Electrical circuits
- B) Engineering drawings
- C) Balance sheets
- D) Flow charts

# Fill in the Blanks

1. Surface roughness refers to the \_\_\_\_\_ irregularities on a surface.
2. The most commonly used roughness parameter is \_\_\_\_\_.
3. Surface roughness is usually measured in \_\_\_\_\_.
4. A \_\_\_\_\_ is commonly used to measure surface roughness.
5. Grinding generally produces a \_\_\_\_\_ surface finish.
6. Surface roughness influences friction and \_\_\_\_\_.
7. The stylus method uses a \_\_\_\_\_ tip to trace the surface.
8. Surface finish symbols are indicated on \_\_\_\_\_ drawings.
9. Lower Ra value indicates a \_\_\_\_\_ surface.
10. Surface roughness is an important aspect of \_\_\_\_\_ control.